

Friends of the Shenandoah River 1460 University Drive Winchester, VA 22601 (540) 665-1286 friendsofshenandoahriver@gmail.com www.fosr.org Friends of the Shenandoah River's 2023 Summer Quantitative *E. coli* Test Results at public recreational use sites on the Main Stem, South Fork and North Fork of the Shenandoah River and the Opequon Creek

These results provide a snapshot of the *E. coli* bacteria concentrations at the designated sites on the date, time, and under the conditions that the water samples were collected.

SITE ID	SITE DESCRIPTION	5/30	6/7	6/14	6/21	6/28	7/5	7/11	7/18	7/26					
	Main-stem Shenandoah River at Castleman's Ferry	-,													
FC08	public boat ramp, Route 7 bridge	35.0	6.3	17.5	81.3	108.1	185.0	39.9	48.0	32.7					
	Main-stem Shenandoah River at Lockes Landing														
FC05	public boat landing	54.8	17.5	76.7	70.8	56.1	56.5	36.9	56.3	37.7					<u> </u>
	Main-stem Shenandoah River at Berry's public boat	47.5	50.4	45.5	40.0	00.0	00.4	040	04.0	07.0					ł
FC01	ramp, Route 50 bridge Main-stem Shenandoah River at Morgan's Ford low	17.5	50.4	45.5	42.0	68.2	23.1	24.3	61.3	27.9					
	H2O bridge public boat landing below confluence														ł
FW35	with Manassas Run	,			·	111.9	70.3	16.1	38.4						
	Main-stem Shenandoah River at Morgan's Ford low														
FW35MID	H2O bridge mid width of river	41.0	73.3	67.3	78.9	52.0	24.6	41.4	14.6	17.5					<u> </u>
	Manassas Run upstream of confluence with main-														
	stem Shenandoah River, just upstream of public														ł
FW36	boat landing	196.8	325.5	248.1	195.6	290.9	325.5	248.1	435.2	344.8					<u> </u>
	SF Shenandoah River at Front Royal public boat	00.4		00.4	00.0	404.7	00.4	40.0	405.0	7.4					ł
FW14	landing off Luray Ave.	20.1	7.5	22.1	26.2	101.7	30.1	19.9	125.9	7.4					
FWAGSP	SF Shenandoah River @ Raymond R. "Andy" Guest Jr Shenandoah River State Park	6.3	17.5	14.8	9.7	63.3	137.6	22.6	42.0	16.1					ł
TWAGSF	SF Shenandoah River at Indian Hollow public boat	0.0	17.5	14.0	5.7	00.0	137.0	22.0	72.0	10.1					
FWIH	launch off Indian Hollow Road	25.9	23.1	14.5	14.4	52.1	44.1	15.6	47.3	8.6					ł
	SF Shenandoah River at reopened White House														ł
FP03	public boat landing on east side of river, river right	26.2	21.6	20.1	40.4	105.0	37.9	14.8	36.4	14.4					-
FP02	SF Shenandoah River at Newport public boat ramp downstream of Riverside Campground/ Kite's Store	27.2	19.9	16.1	67.0	133.3	39.3	10.8	24.6	5.2					ł
FFUZ	downstream of riverside campground/ rite's Store	21.2	19.9	10.1	67.0	133.3	39.3	10.6	24.0	5.2					
FSMB	NF Shenandoah River at Meems Bottom	185.0	40.8	172.3	209.8	228.2	52.9	58.6	34.5	57.3					l
	NF Shenandoah River at Deer Rapids public boat														
FSDR	landing	34.5	17.3	77.6	70.6	56.3	13.5	14.6	38.3	45.7					
	NF Shenandoah River at Strasburg Park public boat										·				1
FSSP	landing	117.8	63.1	117.2	150.0	62.7	48.7	33.6	38.4	206.4					
		•													ł
FCOC	Opequon Creek @ Neill Road ford														<u>. </u>

Previously, Virginia's water quality standard for freshwater beach advisories or closures was a single sample maximum of 235 E. coli CFU/100 ml of sample. Virginia no longer has a single, instantaneous, sample maximum or any criteria for primary recreational contact in freshwaters.

Red indicates that the E. coli concentration exceeded 235 E .coli CFU/100 ml,

Site FSMB, North Fork Shenandoah River at Meems Bottom cover bridge, - River access restricted due to bridge construction downstream

FW35 - several times the site has been dry, the water level had receded moving the bank towrads site FW35MID incictaed by the

←