

Friends of the Shenandoah River 1460 University Drive Winchester, VA 2260 (540) 665-1286 friendsofshenandoahriver@gmail.com

www.fosr.org

Friends of the Shenandoah River's 2023 Summer Quantitative *E. coli* Test Results at public recreational use sites on the Main Stem, South Fork and North Fork of the Shenandoah River and the Opequon Creek

These results provide a snapshot of the *E. coli* bacteria concentrations at the designated sites on the date, time, and under the conditions that the water samples were collected.

| SITE ID | SITE DESCRIPTION | 5/30 | 6/7 | 6/14 | <mark>6/2</mark> 1 | 6/28 | 7/5 | 7/11 | 7/18 | 7/26 | 8/1 | 8/8 | 8/15 | | | |
|---------|--|-------|-------|-------|--------------------|-------|-------|-------|-------|-------|------|-------|-------|--|--|--|
| FC08 | Main-stem Shenandoah River at Castleman's Ferry public boat ramp, Route 7 bridge | 35.0 | 6.3 | 17.5 | 81.3 | 108.1 | 185.0 | 39.9 | 48.0 | 32.7 | 34.4 | 37.3 | 125.0 | | | |
| FCUO | Main-stem Shenandoah River at Lockes Landing | 55.0 | 0.5 | 17.5 | 01.5 | 100.1 | 105.0 | 33.3 | 40.0 | 52.7 | 34.4 | 57.5 | 125.0 | | | |
| FC05 | public boat landing | 54.8 | 17.5 | 76.7 | 70.8 | 56.1 | 56.5 | 36.9 | 56.3 | 37.7 | 23.8 | 93.4 | 42.0 | | | |
| FC01 | Main-stem Shenandoah River at Berry's public boat ramp, Route 50 bridge | 17.5 | 50.4 | 45.5 | 42.0 | 68.2 | 23.1 | 24.3 | 61.3 | 27.9 | 20.7 | 25.6 | 30.1 | | | |
| | Main-stem Shenandoah River at Morgan's Ford low | | | | | | | | | | | | | | | |
| FW35 | H2O bridge public boat landing below confluence with Manassas Run | • | | | | 111.9 | 70.3 | 16.1 | 38.4 | 4 | | | | | | |
| FW35MID | Main-stem Shenandoah River at Morgan's Ford low H2O bridge mid width of river | 41.0 | 73.3 | 67.3 | 78.9 | 52.0 | 24.6 | 41.4 | 14.6 | 17.5 | 20.7 | 104.6 | 25.3 | | | |
| FW36 | Manassas Run upstream of confluence with main- stem Shenandoah River, just upstream of public boat landing | 196.8 | 325.5 | 248.1 | 195.6 | 290.9 | 325.5 | 248.1 | 435.2 | 344.8 | 98.7 | 727.0 | 74.9 | | | |
| FW14 | SF Shenandoah River at Front Royal public boat landing off Luray Ave. | 20.1 | 7.5 | 240.1 | 26.2 | 101.7 | 30.1 | 19.9 | 125.9 | 7.4 | 20.7 | 33.6 | 98.7 | | | |
| FWAGSP | SF Shenandoah River @ Raymond R. "Andy" Guest Jr., Shenandoah River State Park | 6.3 | 17.5 | 14.8 | 9.7 | 63.3 | 137.6 | 22.6 | 42.0 | 16.1 | 9.9 | 10.9 | 21.8 | | | |
| FWIH | SF Shenandoah River at Indian Hollow public boat launch off Indian Hollow Road | 25.9 | 23.1 | 14.5 | 14.4 | 52.1 | 44.1 | 15.6 | 47.3 | 8.6 | 11.1 | 22.3 | 17.1 | | | |
| FP03 | SF Shenandoah River at reopened White House public boat landing on east side of river, river right | 26.2 | 21.6 | 20.1 | 40.4 | 105.0 | 37.9 | 14.8 | 36.4 | 14.4 | 13.7 | 47.3 | 25.9 | | | |
| FP02 | SF Shenandoah River at Newport public boat ramp downstream of Riverside Campground/ Kite's Store | 27.2 | 19.9 | 16.1 | 67.0 | 133.3 | 39.3 | 10.8 | 24.6 | 5.2 | 4.2 | 17.5 | 3.1 | | | |
| FSMB | NF Shenandoah River at Meems Bottom | 185.0 | 40.8 | 172.3 | 209.8 | 228.2 | 52.9 | 58.6 | 34.5 | 57.3 | 28.8 | 235.9 | 24.1 | | | |
| FSDR | NF Shenandoah River at Deer Rapids public boat landing | 34.5 | 17.3 | 77.6 | 70.6 | 56.3 | 13.5 | 14.6 | 38.3 | 45.7 | 30.6 | 17.5 | 16.9 | | | |
| FSSP | NF Shenandoah River at Strasburg Park public boat landing | 117.8 | 63.1 | 117.2 | 150.0 | 62.7 | 48.7 | 33.6 | 38.4 | 206.4 | 36.4 | 44.1 | 18.3 | | | |
| FCOC | Opequon Creek @ Neill Road ford | • | | | | | | | | | | | | | | |

Previously, Virginia's water quality standard for freshwater beach advisories or closures was a single sample maximum of 235 E. coli CFU/100 ml of sample. Virginia no longer has a single, instantaneous, sample maximum or any criteria for primary recreational contact in freshwaters.

Red indicates that the E. coli concentration exceeded 235 E .coli CFU/100 ml,

Site FSMB, North Fork Shenandoah River at Meems Bottom cover bridge, - River access restricted due to bridge construction downstream

FW35 - several times the site has been dry, the water level had receded moving the bank towrads site FW35MID incicated by the